

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 739.8200



September 24, 1987
IP3-87-LMK-210H
IP3-87-056Z

Docket No. 50-286
License No. DPR-64

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

The following is a special report on Penetration Fire Barriers at Indian Point Unit 3, prepared in accordance with Technical Specification 6.9.2.f. The event described is covered by Technical Specification 3.14.C.2.b.

On May 3, 1987 the plant was brought to the cold shutdown condition for a scheduled refueling and maintenance outage. During the course of the outage, a number of penetration fire barriers were opened to allow installation of plant modifications.

Fire watches were established after the penetrations were opened. The plant was brought above cold shutdown in preparation for unit startup on September 2, 1987 and required fire watches were maintained until the penetration fire barriers were resealed and inspected in accordance with the post-maintenance testing program on September 23, 1987.

Very truly yours,

A large, stylized handwritten signature in black ink, appearing to read 'W. A. Josiger'.

William A. Josiger
Resident Manager
Indian Point 3 Nuclear Power Plant

LMK:sn:Kelly3:11

8710060544 870924
PDR ADOCK 05000286
S PDR

IE22
1/0

September 24, 1987
Penetration Fire Barriers
Page 2

cc: Mr. William Russell
Regional Administrator
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

IP3 Resident Inspectors' Office
J.C. Brons, WPO
G.M. Wilverding (SRC), WPO

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339