



John C. Brons
Executive Vice President
Nuclear Generation

October 12, 1989
IPN-89- 062

U.S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, D.C. 20555

Attn: Document Control Desk

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Inservice Inspection Report for Cycle 6/7
Refueling Outage and Preservice Examination
Report for Replacement Steam Generators

Dear Sir:

This letter transmits the reports required by Article IWA-6000 of the ASME Boiler and Pressure Vessel Code Section XI.


Attachment I is a report of the inservice inspection conducted during Cycle 6/7 refueling outage. This inspection completes the examination for the first 40-month period of the Second 10-Year Indian Point 3 Inspection Program. The report consists of extracts from Tabs A, B and C of the Final Weld and Component Examination Inservice Inspection Report.

Attachment II is a report of the preservice inspection of the four replacement steam generators consisting of extracts from Tabs A, B and C of the Final Report.

Attachment III includes the summaries of the steam generator replacement and the hydrostatic tests performed due to this replacement.

Should you or your staff have any questions regarding this matter, please contact Mr. P. Kokolakis of my staff.

Very truly yours,


for John C. Brons
Executive Vice President
Nuclear Generation

Encls.
cc: see next page

8910240290 891012
PDR ADDCK 05000286
Q PNU

A047
11

cc: U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Resident Inspector's Office
Indian Point 3
U.S. Nuclear Regulatory Commission
P.O. Box 337
Buchanan, New York 10511

Mr. J. D. Neighbors, Sr. Project Manager
Project Directorate I-1
Division of Reactor Projects-I/II
U.S. Nuclear Regulatory Commission
Mail Stop 14B2
Washington, D.C. 20555