



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
SAM NUNN ATLANTA FEDERAL CENTER
61 FORSYTH STREET, SW, SUITE 23T85
ATLANTA, GEORGIA 30303-8931

December 14, 2009

Virginia Electric and Power Company
ATTN: Mr. David A. Heacock
President and Chief Nuclear Officer
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: SURRY POWER STATION - NRC SECURITY INSPECTION REPORT
05000280/2009402 AND 05000281/2009402 ERRATA

Dear Mr. Heacock:

On October 7, 2009 the U. S. Nuclear Regulatory Commission (NRC) issued the subject inspection report for the Surry Power Station. In reviewing this report, it was noted that we inadvertently omitted documenting the inspection of the Independent Spent Fuel Storage Installation (ISFSI). Accordingly, we are providing a revised version of Inspection Report 05000280/2009402 and 05000281/2009402 that documents the above change.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system, ADAMS. ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

I apologize for any inconvenience this error may have caused. If you have any questions, please contact me at (404) 562-4540.

Sincerely,

/RA/

Michael E. Ernstes, Chief
Plant Support Branch 2
Division of Reactor Safety

Docket Nos.: 50-280, 50-281
License Nos.: DPR-32, DPR-37

Enclosure: As stated

cc w/encl.: (See page 2)

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.

~~LIMITED INTERNAL~~
~~DISTRIBUTION PERMITTED~~

VEPCO

2

cc w/Encl:
Curtis G. Luffman
Manager
Nuclear Protection Services
Virginia Electric & Power Company
Surry Power Station
5570 Hog Island Road
Surry, VA 23883-0315

Gerald T. Bischof
Site Vice President
Surry Power Station
Virginia Electric and Power Company
5570 Hog Island Road
Surry, VA 23883-0315

Barry Garber
Supervisor
Nuclear Engineering
Virginia Electric and Power Company
Surry Power Station
5570 Hog Island Road
Surry, VA 23883-0315

Leslie N. Hartz
Vice President - Nuclear Support
Services
Dominion Resources Services, Inc.
5000 Dominion Boulevard
Glen Allen, VA 23061

Nelson K. Martin
Manager
Nuclear Fleet Protection Services
Virginia Electric and Power Company
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

Lillian M. Cuoco, Esq.
Senior Counsel
Dominion Resources Services, Inc.
120 Tredegar Street, RS-2
Richmond, VA 23219

Chris L. Funderburk
Director, Nuclear Licensing &
Operations Support
Virginia Electric and Power Company
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

Virginia Electric and Power Company
ATTN: Mr. David A. Heacock
President and Chief Nuclear Officer
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: SURRY POWER STATION - NRC SECURITY INSPECTION REPORT
05000280/2009402 AND 05000281/2009402 ERRATA

Dear Mr. Heacock:

On October 7, 2009 the U. S. Nuclear Regulatory Commission (NRC) issued the subject inspection report for the Surry Power Station. In reviewing this report, it was noted that we inadvertently omitted the inspection of the Independent Spent Fuel Storage Installation (ISFSI). Accordingly, we are providing a revised version of Inspection Report 05000280/2009402 and 05000281/2009402 that documents the above change.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system, ADAMS. ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

I apologize for any inconvenience this error may have caused. If you have any questions, please contact me at (404) 562-4540.

Sincerely,
/RA/
Michael E. Ernstes, Chief
Plant Support Branch 2
Division of Reactor Safety

Enclosure: As stated

cc w/encl.: (See page 2)

☒ PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE ☒ NON-SENSITIVE
ADAMS: X Yes ACCESSION NUMBER: _____ ☒ SUNSI REVIEW COMPLETE

OFFICE	RII:DRS	RII:DRS	RII:DRS	RII:DRP	RII:DRS	
SIGNATURE	/RA/	/RA/	/RA/	/RA/	/RA/	
NAME	J. Tornow	K. Davis	J. Shehee	G. McCoy	M. Ernstes	
DATE	12/14/2009	12/14/2009	12/14/2008	12/7/2009	12/14/2009	
E-MAIL COPY?	YESNO	YESNO	YESNO	YESNO	YESNO	YESNO

OFFICIAL RECORD COPY DOCUMENT NAME:
GI:\PSBII\REACTORS\SURRY\Reports\2009\Surry Sec Insp Report 2009402
and Errata Letter.doc