

William J. Cahill, Jr.  
Vice President

Regulatory

File Cy.



Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

December 28, 1972

Re Indian Point Unit No. 2  
AEC Docket No. 50-247

Mr. Angelo Giambusso, Deputy Director  
for Reactor Projects  
Directorate of Licensing  
U. S. Atomic Energy Commission  
Washington, D. C. 20045

Dear Mr. Giambusso


The Directorate of Licensing letter, dated December 19, 1972, requested a review of Indian Point Unit No. 2 to determine whether a postulated pipe failure in the main steam or feedwater lines outside of containment would result in damage to the auxiliary feedwater system.

We plan to submit the analysis of this postulated accident situation for Indian Point Unit No. 2 by March 30, 1973. If the results of the analysis indicate that modifications to the facility are necessary, we will also provide a description and estimates of the schedule for design, fabrication and installation of the modifications.

Very truly yours

William J. Cahill, Jr.  
Vice President

md



8111090504 721228  
PDR ADOCK 05000247  
PDR

82  
fw