

JAN 15 1974

Docket No. 50-247

Consolidated Edison Company  
of New York, Inc.  
ATTN: William J. Cahill, Jr.  
Vice President  
4 Irving Place  
New York, New York 10003

Gentlemen:

As discussed with your staff by telephone, this letter is to correct minor errors made in Change No. 2 issued as an Attachment to Amendment No. 3 and dated August 9, 1973.

The following corrections should be made in Appendix A of License No. DPR-26:

1. Section 3.1.F - LEAKAGE OF REACTOR COOLANT

- a. Paragraph 3, 3rd sentence - after the words "is within the guidelines of . . .", add the number "10".
- b. Paragraph 4 of the Specifications should read as follows:  

"4. When the reactor is critical and above 2% power, two reactor coolant leak detection systems of different principles shall be in operation with one of the two systems sensitive to radioactivity. The system sensitive to radioactivity may be out-of-service for 48 hours provided two other systems are available."

2. Section 4, Table 4.1-2, Footnote (21) - The Specification number should read "3.1.F.4" instead of "3.1.F.5".

Sincerely,

Original signed by  
Donald J. Skovholt

Donald J. Skovholt  
Assistant Director for  
Operating Reactors  
Directorate of Licensing

8111100219 740115  
PDR ADDCK 05000247  
P PDR

Consolidated Edison Company  
of New York, Inc.

- 2 -

JAN 15 1974

cc: Leonard M. Trosten, Esquire  
LeBoeuf, Lamb, Leiby & MacRae  
1757 N Street, N. W.  
Washington, D. C. 20036

Hendrick Hudson Free Library  
31 Albany Post Road  
Montrose, New York 10548

DISTRIBUTION  
Docket File  
AEC PDR  
RP Reading  
Branch Reading  
JRBuchanan  
TBAbernathy  
DJSkovholt  
RTedesco  
RDeYoung  
TJCarter  
SVarga  
RJSchemel  
RWWoodruff(2)  
SATEets  
MJinks (4)  
NDube  
BScharf (15)  
RO (3)  
OGC  
ACRS (16)  
SKari  
SATEets

OFFICE ➤	L:ORB#1	L:ORB#1	L:ORB#1	L:OR		
SURNAME ➤	SATEets:dc	RWWoodruff	RJSchemel	DJSkovholt		
DATE ➤	1/10/74	1/10/74	1/15/74	1/15/74		