



77
Telegram

911P EST NOV 5 71 PB504

Q NNG519 (AT 309NN327519)PD IPM108D NYK

0659P EST11/05/71

ZCZC 327 XNT0884 NYND PI GPG PDB FAX NEW YORK NY 5 549P EST
JAMES O REILLY, U S ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE REGION 1
970 BROAD ST NEWARK NJER

BT

IN COOPLIANCE WITH PARAGRAPH 6.6.1 OF APPENDIX A-
TECHNICAL SPECIFICATIONS FOR CON ED I P NUCLEAR UNIT
FACILITY OPERATING LICENSE #DPR-26 AND CONFIRMING
VARIOUS TELEPHONE CONVERSATIONS BETWEEN CON EDISON
PERSONNEL AND VARIOUS PERSONNEL OF REGION I COOPLIANCE
PLUS DIRECTOR OF REGULATIONS (USAEC). PLEASE BE

8F-1201 (R5-69)

ADVISED THAT ON 11-4 AT APPROXIMATELY 1900 HOURS A
WIRE AS OF YET UNDETERMINED ORIGIN WAS DETECTED IN
UNIT #2 PRIMARY AUXILIARY BUILDING (PAB). THE FIRE
WAS FOUND AT THE EAST END OF THE PAB 80 FT ELEVATION
INVOLVING A TEMPORARY WOODEN SHED (THE CON ED OPERATOR
WHO DISCOVERED THE FIRE IMMEDIATELY REPORTED SAME TO
CENTRAL CONTROL ROOM OPERATOR WHO IN TURN CALLED IN
LOCAL FIRE DEPARTMENT FOR ASSISTANCE). THE FIRE WAS
CONTAINED AND EXTINGUISHED IN APPROXIMATELY 2 HOURS
AND THE VARIOUS FIRE DEPARTMENTS WHO HAD RESPONDED
TO REQUEST FOR ASSISTANCE REMAINED AT SITE
UNTIL APPROXIMATELY 23 HOURS.

A SURVEY OF FIRE AREA REVEALED EXTENSIVE DAMAGE TO

8F-1201 (R5-69)

8110240272 711005
PDR ADOCK 05000247
S PDR



Telegram

GARIOUS ELECTRICAL SWITCHGEAR LOCATED IN EAST END OF
PAB AND SMOKE, HEAT AND WATER DAMAGE TO OTTER VARIOUS
EQUIPMENT IN IMMEDIATE VICINITY. AN INVESTIGATION AS
TO THE CAUSE OF THE FIRE AND THE EXTENT OF THE DAME
IS PRESENTLY UNDERWAY.

AT TTE TIME OF TTE FIRE THE REACTOR CORE WAS LOADED
IN THE REACTOR VESSEL AND THE UPPER INTERNAL PACKAGE
AND REACTOR VESSEL HEAD NOT INSTALLED. DURING THE EMERGENCY
INCREASED SURVEILLANCE OF BORIC ACID CONCENTRATION
OF THE REACTOR COOLANT WAS MAINTAINED.
NO SIGNIFICANT CHANGE IN THE BORIC ACID CONTENT WAS
OBSERVED AND AT ALL TIMES THE CONCENTRATION REMAINED
IN EXCESS OF TTE TECHNICAL SPECIFICATION REQUIREMENT

OF 2000 PPM OR GREATER.

A WRITTEN REPORT REQUIRED BY PARAGRAPH 6.6.1 OF THE
TECHNICAL SPECIFICATION WILL BE FORWARDED WITHIN THE
REQUIRED 10 DAYS

WILLIAM E CALDWELL JR VICE PRESIDENT

6.6.1 #DPR-26 11-4 1900 #2 2 2300 2000 6.6.1 10.

NNNN(0848P EST)

MEMO ROUTE SLIP		See me about this.	For concurrence.	For action.
Form AEC-93 (Rev. May 14, 1947) AECM 0240		Note and return.	For signature.	For information.
TO (Name and unit)	INITIALS	REMARKS		
cc w/enclosure:		RE: CONSOLIDATED EDISON COMPANY (INDIAN POINT 2)		
E. G. Case, DRS(3)		DOCKET NO. 50-247		
R. S. Boyd, DRL(2)	DATE			
R. C. DeYoung, DRL(2)		Attached for your information is a copy of a TWX		
D. J. Skoyholt, DRL(3)				
TO (Name and unit)	INITIALS	REMARKS		
H. R. Denton, DRL(2)		Report dated November 5, 1971, from the subject		
A. Giambusso, w/o encl.		licensee reporting an abnormal occurrence, i.e.,		
L. Kornblith, w/o encl.	DATE			
R. H. Engelken, w/o encl		fire at Indian Point 2 on November 4, 1971.		
J. B. Henderson, CO				
TO (Name and unit)	INITIALS	REMARKS		
M. L. Ernst, CO				
W. S. Farmer, CO				
CO Files	DATE			
PDR				
NSIC				
FROM (Name and unit)	REMARKS			
✓ DR Central Files				
R. T. Carlson, Acting				
Chief, Reactor Testing				
& Operations Branch,				
CO				
PHONE NO.	DATE			
	11/17/71			

USE OTHER SIDE FOR ADDITIONAL REMARKS

☆ GPO: 1971 O-422-304

Here fill