

Vice President
Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 480-3819

DR Central file

September 26, 1972


Re Indian Point Unit No. 2
Docket No. 50-247

Mr. Frank E. Kreusi, Director
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Kreusi

On August 28, 1972, Consolidated Edison notified the Commission by telephone regarding the discovery of areas in which some piping and welds were not in accordance with specifications. At that time, Consolidated Edison stated that a written report would be submitted within thirty days. Accordingly, enclosed herewith is a report entitled, "Investigation of Welds and Pipe Wall Thickness in Vent and Drain Assemblies", dated September 26, 1972, for the above-referenced plant.


Very truly yours



William J. Cahill, Jr.
Vice President

enc.
md

Copy to James P. O'Reilly, Director
Regulatory Operations
Region 1
U. S. Atomic Energy Commission
970 Broad Street
Newark, N. J. 07102



8110240332 720926
PDR ADOCK 05000247
S PDR

*Misc
appl.*