

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-3819


Regulatory Docket File

December 10, 1976

Re: Indian Point Unit No. 2
Docket No. 50-247



Director of Nuclear Reactor Regulation
ATTN: Mr. Robert W. Reid, Chief
Operating Reactors Branch # 4
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



Dear Sir:

In accordance with my letter to you of July 19, 1976, enclosed are three (3) copies of a report entitled, "Cycle 2 Startup Physics Test Report, Indian Point Unit No. 2". This report contains a complete summary of those startup physics tests performed during the return to service following the first refueling outage.

Very truly yours,

William J. Cahill, Jr.
William J. Cahill, Jr.
Vice President

LFL/mmg

Copy to: Mr. James P. O'Reilly, Director (2 copies)
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Ave.
King of Prussia, Pa 19406

Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (25 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (2 copies)
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

12723

8111070359 761210
PDR ADOCK 05000247
PDR