

William J. Cahill, Jr.  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

REGULATORY DOCKET FILE COPY

February 17, 1978  
Re: Indian Point Unit No. 2  
Docket No. 50-247

Mr. Boyce H. Grier, Director  
Office of Inspection and Enforcement  
Region 1  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406



Dear Mr. Grier:

The attached report (TEIR-77-2-16) is being submitted for your information.

Very truly yours,

*William J. Cahill, Jr.*  
William J. Cahill, Jr.  
Vice President

WJC/nvg

780680049

8110310850 780217  
PDR ADOCK 05000247  
S PDR

A002/s \*  
0/1

# LICENSE EVENT REPORT

TEIR-2-16

CONTROL BLOCK: 

--	--	--	--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
NY I P S 2	00-000000-00	41111	99
9 14	15 25	26 30	31 32

CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
	0	L	050-0247	121577	021778
57 58	59	60	61 68	69 74	75 80

EVENT DESCRIPTION

DURING NORMAL OPERATION, NO. 23 AUXILIARY BOILER FEED PUMP WAS REMOVED FROM SERVICE FOR PREVENTIVE MAINTENANCE TO REPLACE ITS MOTOR, WHICH HAD BEEN SPARKING DURING ITS LAST SURVEILLANCE TEST. MOTOR DRIVEN AUXILIARY BOILER FEED PUMP 21 AND STEAM DRIVEN PUMP 22 WERE BOTH VERIFIED OPERABLE. THE MOTOR WAS REPLACED AND THE PUMP WAS RETURNED TO AN OPERABLE STATUS (TEIR-77-2-16).

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
H H	E	MOTORX	N	W120	N
9 10	11	12 17	43	44 47	48

CAUSE DESCRIPTION

NO. 23 AUXILIARY BOILER FEED PUMP WAS REMOVED FROM SERVICE AS A RESULT OF A SPARKING MOTOR (WESTINGHOUSE, 400 BHP, DWG 861C800).

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
E	100	NA	B	SURVEILLANCE TESTING
9	10 12 13	13	44 45 46	80

  

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z	Z	NA	NA
9	10	11 44	45 80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	Z-	NA
9 11	12	13 80

PERSONNEL INJURIES

NUMBER	DESCRIPTION
000	NA
9 11	12 80

PROBABLE CONSEQUENCES

NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
Z	NA
9 10	80

PUBLICITY

NA

ADDITIONAL FACTORS