

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N.Y. 10003 Telephone (212) 460-5133

August 18, 1978

Docket No. 50-247

Indian Point Unit No. 2

Director of Nuclear Reactor Regulation

Mr. A. Schwencer, Chief

Operating Reactors Branch # 1 Division of Operating Reactors

U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Schwencer:

In accordance with our May 4, 1978 letter to you, enclosed are three (3) copies of a report entitled "Indian Point Unit No. 2 Cycle 3 Startup Physics Test Report." This report contains a summary of startup physics tests performed during the return to service following the second refueling outage.

Re:

Very truly yours

encl. SEE REPORTS.

Vice President

Mr. Boyce H. Grier, Director (2 copies) Office of Inspection and Enforcement Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pa 19406

Director of Nuclear Reactor Regulation

ATTN:

MEGGANIAN BOOKER FREE COMP Dr. Ernst Volgenau, Director (36 copies)

Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

782360144