


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-3819




Regulatory

File Cya

Re Indian Point Unit
Docket No. 50-247
R.O.-76-2-10(B)
R.O.-76-2-11(B)
R.O.-76-2-2(B) - Update Report
R.O.-76-2-3(B) - Update Report

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406



Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-26, the attached reports of Reportable Occurrences R.O.-76-2-10(B) and R.O.-76-2-11(B) are submitted. These reports fulfill the requirement for written reports within 30 days of Reportable Occurrences and are in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Also attached are update reports for Reportable Occurrences R.O.-76-2-2(B) and R.O.-76-2-3(B) which revise the violation codes (line No. 7 - column 48) contained in the previous reports submitted on February 13, 1976.

Three copies of this letter and the attachments are enclosed as required.

Very truly yours

William J. Cahill, Jr.
Vice President

mrh

Copy to Director of Nuclear Reactor Regulation
ATTN: Mr. Donald F. Knuth, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William F. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8111090030 760409
PDR ADOCK 05000247
S PDR

3798