

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME: 01 N Y I P S 2 14 15 25 26 30 31 32
 LICENSE NUMBER: 00-000000-00
 LICENSE TYPE: 41111
 EVENT TYPE: 03

CATEGORY: 01 CONT 57 58
 REPORT TYPE: L 59
 REPORT SOURCE: L 60
 DOCKET NUMBER: 050-0247 61 68
 EVENT DATE: 022676 69 74
 REPORT DATE: 032576 75 80

EVENT DESCRIPTION

02 During normal operation, process radiation monitors R-11 and R-12 became
 03 inoperable due to bearing failure in the motor for their common sample
 04 pump. The humidity and condensate flow systems, as well as the instru-
 05 mentation required for a water inventory balance, were operable. The
 06 compressor was repaired and both monitors returned to service (Cont'd)

SYSTEM CODE: 07 M C 9 10
 CAUSE CODE: E 11
 COMPONENT CODE: M O T O R X 12 17
 PRIME COMPONENT SUPPLIER: N 43
 COMPONENT MANUFACTURER: G O 8 0 44 47
 VIOLATION: N 48

CAUSE DESCRIPTION

08 The bearings of the General Electric, Model K145 BK 2364A, 3 phase,
 09 60 HZ, 460V, 2 HP motor failed, rendering process monitors R-11 and
 10 R-12 inoperable.

FACILITY STATUS: 11 E 9
 % POWER: 097 10 12 13
 OTHER STATUS: NA 44
 METHOD OF DISCOVERY: A 45
 DISCOVERY DESCRIPTION: NA 46

FORM OF ACTIVITY RELEASED: 12 Z 9
 CONTENT OF RELEASE: NA 10 11
 AMOUNT OF ACTIVITY: NA 44
 LOCATION OF RELEASE: NA 45

PERSONNEL EXPOSURES

13 NUMBER: 000 11
 TYPE: Z 12
 DESCRIPTION: NA 13

PERSONNEL INJURIES

14 NUMBER: 000 11
 DESCRIPTION: NA 12

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z 9
 DESCRIPTION: NA 10

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 (Event Descrip. Cont'd) within the Tech. Spec. time limit. (RO-76-2-8(B))

19 8111090049 760325
 PDR ADDOCK 05000247
 S PDR

NAME: Michael Shatkouski

PHONE: (914)-739-8823