Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y 10003 Telephone (212) 460-3819

March 10, 1976

Re Indian Point Unit No.2 Docket No. 50-247 R.O. -76-2-6(B) R.O. -76-2-7(B)

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement Region 1 U.S. Nuclear Regulatory Commission King of Prussia, PA 19406

Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-26, the attached reports of Reportable Occurrences R.O. -76-2-6(B) and R.O. -76-2-7(B) are submitted. These reports fulfill the requirement for written reports within 30 days of Reportable Occurrences and are in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachments are enclosed as required.

Very truly yours

Enc. mrb

William J. Cahill, Jr.

Vice President

Copy to Director of Nuclear Reactor Regulation
ATTN: Mr. Donald F. Knuth, Director (30Copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William F. McDonald, Director (3 Copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission

Washington, D. C. 20555

washington, D. C. 2035