LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT ALL REQUIRED INFORMATION) LICENSEE LICENSE EVENT. NAME LICENSE NUMBER TYPE Ρ 0 - 0sl 411 111 1 0 1 32 REPORT REPORT CATEGORY DOCKET NUMBER TYPE REPORT 0 8 0 0 1 CON'T 0 5 01910 0 0 -02 4 7 5 L 5 58 60 59 61 EVENT DESCRIPTION | During cold shutdown condition for a scheduled outage, periodic surveil-02 8 9 80 03 | lance test PT-M14A [Containment Spray Pump Functional Test] was not per-8.9 80 04 formed at the required time frequency. The test was completed success-**A** 0 80 05 prior to returning the unit to service. [A.O.-75-2-15(B)]. f_{11}]] v 8 9 80 06 8 9 80 PRIME SYSTEM CAUSE COMPONENT COMPONENT CODE MANUFACTURER CODE COMPONENT CODE SUPPLIER VIOLATION IA 07 F NSTRU IΤ N Z | 9 | 9 | 9 Y 8 9 10 11 12 43 48 CAUSE DESCRIPTION Test could not be performed since the reactor trip breakers, which are 08 8 q 80 og required to be operable to accomplish the test, were isolated to provide 8 9 80 10 protection for workers performing maintenance during the outage 89 80 FACILITY METHOD OF % POWER OTHER STATUS STATUS DISCOVERY DISCOVERY DESCRIPTION 11 G 0 0 1 0 N.A A N.A Q 10 12 13 44 45 46 8Ö FORM OF CONTENT ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE 1 2 ΖI IN Ν 10 11 80 PERSONNEL EXPOSURES NUMBER DESCRIPTION TYPE 13 -11 12 13 80 59 PERSONNEL INJURIES NUMBER DESCRIPTION 010 N 8 9 11 12 80 PROBABLE CONSEQUENCES 15 N.A. 80 LOSS OR DAMAGE TO FACILITY DESCRIPTION TYPE Z N.A. 8 9 10 80 PUBLICITY 17 8111090239 750903 N.A. PDR ADOCK 05000247 8 Q 80 ADDITIONAL FACTORS 18 By submittal dated 8/21/75, a tech. spec. change was requested which 8 9would clarify surveillance requirements and avoid this type of conflict 50 with personnel protection considerations. 19 7 8 9 NAME: Michael 80 PHONE: (914)-739-8823 Shatkouski

GPO 881.667