



Carl L. Newman
Vice President

Regulatory Docket File

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133

July 30, 1975

RE: Indian Point Unit No. 2
Docket No. 50-247
A.O.-5-2-11 (B)



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-26, the attached report of Abnormal Occurrence A.O.-5-2-11 (B) is submitted. This report fulfills the requirement for a written report within 30 days of an Abnormal Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 3. Three copies of this letter and the attachment are enclosed as required.

Very truly yours,

Carl L. Newman
Vice President

Encl.
mp

Copy to: Mr. Donald F. Knuth, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8111090265 750730
PDR ADDCK 05000247
S PDR

8551

LICENSEE EVENT REPORT

Regulatory Docket File

CONTROL BLOCK:

1 2 3 4 5 6 7 8 9 0

Facility w/Ltr Dated 1-30-95

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER											LICENSE TYPE					EVENT TYPE	
01	N	Y	I	P	S	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1							
7	8	9	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32										

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CON'T	P	O	L	L	0	5	0	-	0	2	4	7	0	6	3	0	7	5	0	7	3	0	7	5
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

EVENT DESCRIPTION

02 During normal operation, while reviewing the results of a periodic surveillance test,
 03 it was found that channel two of the containment spray logic was not completely tested
 04 at the required time frequency. The remaining channels were tested and operable.
 05 Channel two was subsequently tested satisfactorily. A.O.-5-2-11(B)
 06

SYSTEM CODE	CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION					
07	I	B	E	I	N	S	T	R	U	N	X	9	9	9	Y	
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION

08 A Reese Inc. test switch PC-449C Catalog No. 40704-000 was found to be defective.
 09 The channel was tested by an alternate method. The defective switch will be replaced
 10 during a future outage.

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
11	E	100	0	NA	B	Periodic Surveillance Test				
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE				
12	Z	NA	NA				
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	000	Z NA				
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	000 NA				
7	8	9	11	12	80

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	Z NA			
7	8	9	10	80

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19 NA

Michael Shatkouski

914-739-8823

NAME:

PHONE:

UNITED STATES DEPARTMENT OF JUSTICE

0 0 0

IV

0 0 0

IV

R

S

F

17

4

1 0 4 0

1 1 7

3

RECEIVED DIRECTOR, FBI

UNITED STATES DEPARTMENT OF JUSTICE

WASHINGTON, D. C. 20535

TO: DIRECTOR, FBI (100-441171)

FROM:

SAC, NEW YORK (100-158711)

DATE:

1

SUBJECT: MURDER OF MARTIN LUTHER KING, JR.;

RE: NEW YORK TELETYPE TO BUREAU, AUGUST 1, 1975.

FOR INFORMATION OF THE BUREAU, THE FOLLOWING IS A SUMMARY OF THE MATTER:

ON AUGUST 1, 1975, THE NEW YORK OFFICE RECEIVED A TELETYPE FROM THE

FOLLOWING IS A SUMMARY OF THE MATTER:

ON AUGUST 1, 1975, THE NEW YORK OFFICE RECEIVED A TELETYPE FROM THE

FOR INFORMATION OF THE BUREAU, THE FOLLOWING IS A SUMMARY OF THE MATTER:

ON AUGUST 1, 1975, THE NEW YORK OFFICE RECEIVED A TELETYPE FROM THE

RECEIVED
U.S.N.R.C.
AUG 1 1975

KING OF PRUSSIA, PA.

40

**NRC DISTRIBUTION FOR PART 50 DOCUMENT MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 8551
FILE: INCIDENT REPORT FILE

FROM: Con. Edison Co. of N.Y. New York, N.Y. 10003 Carl L. Newman		DATE OF DOC 7-30-75	DATE REC'D 8-12-75	LTR XX	TWX	RPT	OTHER
TO: Mr. J. P. O'Reilly		ORIG 1 signed	CC	OTHER	SENT AEC PDR <u>XX</u> SENT LOCAL PDR <u>XX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-247		

DESCRIPTION: Ltr trans the following:

PLANT NAME: Indian Pt. 2

ENCLOSURES: Licensee Event Report A0-50-247/
5-2-11 on 6-30-75 re channel two of the
containment spray logic was no completely
tested at the required time frequency...

(1 cy encl rec'd)
Do Not Remove
ACKNOWLEDGED

FOR ACTION/INFORMATION DHL 8-14-75

- | | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)
W/ Copies | SCHWENCER (L)
W/ Copies | ZIEMANN (L)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (L)
W/ Copies | STOLZ (L)
W/ Copies | DICKER (E)
W/ Copies | LEAR (L)
W/ Copies |
| PARR (L)
W/ Copies | VASSALLO (L)
W/ Copies | KNIGHTON (E)
W/ Copies | SPELS
W/ Copies |
| KNIEL (L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

*Reid
w/3 cop*

INTERNAL DISTRIBUTION

- | | | | | |
|---|--|--|---|--|
| REG FILE
NRC PDR
OGC, ROOM P-506A
GOSSICK/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L)
DEYOUNG (L)
SKOVHOLT (L)
GOLLER (L) (Ltr)
P. COLLINS
DENISE
REG OPR
FILE & REGION (2)
MIPC/PE (3)
STEELE | TECH REVIEW
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
**STELLO
**HOUSTON
**NOVAK
ROSS
IPPOLITO
TEDESCO
J. COLLINS
LAINAS
BENAROYA
VOLLMER | DENTON
**GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR
HARLESS | LIC ASST
R. DIGGS (L)
H. GEARIN (L)
E. GOULBOURNE (L)
P. KREUTZER (E)
J. LEE (L)
M. RUSHBROOK (L)
S. REED (E)
M. SERVICE (L)
S. SHEPPARD (L)
M. SLATER (E)
H. SMITH (L)
S. TEETS (L)
G. WILLIAMS (E)
V. WILSON (L)
R. INGRAM (L)
M. DUNCAN (E) | A/T IND.
BRAITMAN
SALTZMAN
MELTZ

PLANS
MCDONALD
CHAPMAN
DUBE (Ltr)
E. COUPE
PETERSON
HARTFIELD (2)
KLECKER
EISENHUT
WIGGINTON
F. WILLIAMS
HANAUER |
|---|--|--|---|--|

EXTERNAL DISTRIBUTION

- | | | |
|-------------------------------------|--------------------------------|---|
| 1 - LOCAL PDR <u>Montrose, N.Y.</u> | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201
GT |
| 5 - ACRS SENT TO LIC ASST R. Ingram | | |
| ** SEND ONLY TEN DAY REPORTS | | |

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

A. IE Inspection Report No. _____

Transmittal Date : _____

Distribution:
IE Chief, FS&EB
IE:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
IE Files
IE Chief, M&PPB
L:D/D for Reactor Project

B. IE Inquiry Report No. _____

Transmittal Date : _____

Distribution:
IE Chief, FS&EB
IE:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ
DR Central Files
IE Files

C. Incident Notification From: Commonwealth Edison Company 50-249
(Licensee & Docket No. (or License No.))

Transmittal Date : June 30, 1975 Dresden Station Unit 3

Distribution:
IE Chief, FS&EB
IE:HQ (4)
Licensing (4)
DR Central Files
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
IE Files

