

William J. Cahill, Jr.
Vice President


Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

Regulatory Docket File

February 18, 1975

Re Indian Point Unit No. 2
Docket No. 50-247

Mr. George Lear, Chief
Operating Reactors Branch #3
Directorate of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Dear Mr. Lear

As stated in our letter of January 20, 1975, Consolidated Edison conducted a re-investigation of the possible failure of non-Category I equipment in light of your request of December 18, 1974. Our review has been completed and it was found that no additional corrective measures beyond those taken in response to the Directorate of Licensing letter dated September 26, 1972 are necessary to protect safety-related equipment from potential flooding or chemical release following the failure of non-Category I equipment. The measures that were taken were as follows:


- (1) Level alarms were installed in the common turbine hall for Indian Point Units 1 and 2. These alarms would detect rising water following a break in a circulating water line and allow the operator to trip the pump.
- (2) Modifications were made to the doors at the 19'8" elevation of the Auxiliary Boiler Feed Pump Building, and at the 19' elevation of the Primary Auxiliary Building. These modifications assure adequate drainage under the postulated conditions of failure.

The above modifications were completed by May 1973 and therefore added protection is provided above that incorporated in the original design such that failure of non-Category I equipment will not adversely affect the performance of safety-related equipment required for the safe shutdown of the facility or for limiting the consequences of an accident.

Very truly yours

William J. Cahill, Jr.
Vice President

mrh



8111090358 750218
PDR ADOCK 05000247
PDR

1878

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 1878

FILE: INCIDENT REPORT

FROM: Con. Edison Co. of N.Y. New York, N.Y. 10003 Wm. J. Cahill, Jr.		DATE OF DOC 2-18-75	DATE REC'D 2-20-75	LTR XX	TWX	RPT	OTHER
TO: Mr. George Lear		ORIG 1 signed	CC	OTHER	SENT AEC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-247		

DESCRIPTION: Ltr re our 1-20-75 ltr...furn info re possible failure of non-Category I equipment in light of your request of 12-18-74.....

ENCLOSURES:

ACKNOWLEDGED
Do Not Remove

PLANT NAME: Indian Pt. 2

FOR ACTION/INFORMATION

DHL 2-21-75

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	✓ FEAR (S) W/4 Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506-A GOSSICK /STAFF CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (PWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG OPR FILE & REGION T.R. WILSON	TECH REVIEW SCHROEDER MACCARRY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA STEELE VOLIMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC. ASST. DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S)	A/T IND BRAITMAN SALTZMAN B. HURT PLANS MCDONALD CHAPMAN DUBE w/input E. COUPE ✓ R. Hartfield (2) ✓ KLECKER ✓ F. WILLIAMS No (4)
---	--	--	--	---

EXTERNAL DISTRIBUTION

1-LOCAL PDR Montrose, N.Y.	(1) (2) (10) - NATIONAL LABS	1-PDR SAN/LA/NY
1-TIC (ABERNATHY)	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/AGBABIAN	1-AGMED (RUTH GUSSMAN) RM B-127 G.T.
1-NEWTON ANDERSON		1-J. RUNKLES, RM E-201 G.T.
5-ACRS SENT TO LIC. ASST. S. Teets 2-21-75		