

November 6, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-35

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Abnormal Occurrence No. 4-2-35 is submitted.

The occurrence is the type defined by Technical Specification 1.8.b and relates to the refueling water storage tank containing less than 350,000 gallons of water as required by specification 3.3.A.1.a.

Following a filling operation of the refueling water storage tank, it was determined that the amount of water initially contained in the tank had been about 3,600 gallons less than required. The unit was operating at 47% of rated power at the time of the occurrence.

Our preliminary review of this occurrence indicates that the safety implications are not significant since the amount of water in the tank was above that indicated necessary by the accident analysis.

This abnormal occurrence was identified on November 6, 1974 and reported to Mr. Anthony Fasano of your office the same day.

Walter Stein

Walter Stein, Manager
Nuclear Power Generation

cc/ Edson G. Case

B111090378 741106
PDR ADOCK 05000247
S PDR


A.O. 4

REGULATORY DOCKET FILE COPY

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003

November 6, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-35



Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Abnormal Occurrence No. 4-2-35 is submitted.

The occurrence is the type defined by Technical Specification 1.8.b and relates to the refueling water storage tank containing less than 350,000 gallons of water as required by specification 3.3.A.1.a.

Following a filling operation of the refueling water storage tank, it was determined that the amount of water initially contained in the tank had been about 3,600 gallons less than required. The unit was operating at 47% of rated power at the time of the occurrence.


Our preliminary review of this occurrence indicates that the safety implications are not significant since the amount of water in the tank was above that indicated necessary by the accident analysis.

This abnormal occurrence was identified on November 6, 1974 and reported to Mr. Anthony Fasano of your office the same day.

Walter Stein

Walter Stein, Manager
Nuclear Power Generation

cc/ Edson G. Case



DUPE

8/11090378

11502

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 11502

FILE: _____

FROM: Consolidated Edison New York, NY W Stein		DATE OF DOC 11-6-74	DATE REC'D 11-11-74	LTR	TWX	RPT	OTHER FACSIMILE
TO: Mr. O'Reilly		ORIG NONE SIGNED	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-247		

DESCRIPTION:
Ltr re Abnormal Occurrence #4-2-35 on 11-6-74 concerning the refueling water storage tank containing less water than required by tech specs.....

PLANT NAME: Indian Point #2

ENCLOSURES:

DO NOT REMOVE

FOR ACTION/INFORMATION 11-29-74 ehf

BUTLER (L) W/ Copies	SCHWENGER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

REG FILE	TECH REVIEW	DENTON	LIC ASST	A/T IND
AEC PDR	SCHROEDER	GRIMES	DIGGS (L)	BRAITMAN
CGC, ROOM P-506A	ACCARY	GAMMILL	GEARIN (L)	SALTZMAN
MUNTZING STAFF	RIGHT	RASTNER	GOULBOURNE (L)	B. HURT
CASE	AWLICKI	BALLARD	KREUTZER (E)	PLANS
GIAMBUSSO	SHAO	SPANGLER	LEE (L)	MCDONALD
BOYD	TELLO	ENVIRO	MAIGRET (L)	CHAPMAN
MOORE (L) (BWR)	TOUSTON	MULLER	REED (E)	DUBE w/input
DEYOUNG (L) (PWR)	OVAK	DICKER	SERVICE (L)	E. COUPE
SKOVHOLT (L)	ROSS	KNIGHTON	SHEPPARD (L)	
GOLLER (L)	IPPOLITO	YOUNGBLOOD	SLATER (E)	THOMPSON (2)
P. COLLINS	TODESCO	REGAN	SMITH (L)	LECKER
DENISE	LONG	PROJECT LDR	TEETS (L)	EISENHUT
REG OPR	AINAS	HARLESS	WILLIAMS (E)	
FILE & REGION (3)	NAROYA		WILSON (L)	
MORRIS	VOLIMER			
STEELE				

EXTERNAL DISTRIBUTION As R

LOCAL PDR <i>Montrose, N.Y.</i>	NATIONAL LABS	1 - PDR SAN/LA/NY
TIC (ABERNATHY) (1)(2)(10)	ASLSPNE (W. 520, Rm 520)	1 - BROOKHAVEN NAT LAB
NSIC (BUCHANAN)	W. PENNINGTON, Rm E-201 GT	1 - G. ULRIKSON, ORNL
1 - ASLB	B&M SWINEBROAD, Rm E-201 GT	1 - AGMED (RUTH GUSMAN)
1 - Newton Anderson	CONSULTANTS	Rm B-127 GT
ACRS HOLDING	NEWARK BLUME/AGBIAN	1 - R. D. MUELLER, Rm E-201
Sent to Lic Asst. <i>Tents</i>		GT