

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

REGULATORY DOCKET FILE COPY

September 16, 1977

Re: Indian Point Unit 2
Docket No. 50-247

U. S. Nuclear Regulatory Commission
Office of Management Information & Program Control
Operating Data Branch, 12105 MNBB
Washington, D. C. 20555

Gentlemen

In response to your August 26, 1977 request for verification of attached data, the information is correct as submitted. Please be advised, however, that the effluents reported are according to site specifications which consist of Unit 1, 2 and 3 release information. Regarding your inquiry concerning the use of the symbol for "less than", this symbol identifies the lowest detectable limit for the isotope in the sample being measured and signifies that the actual value is still lower because no reading could be obtained. However, when this occurs, the lowest detectable limit value is used in calculating total effluent discharge of the isotope.

Very truly yours



8111230217 770916
PDR ADDCK 05000247
PDR

772630090