

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	I	P	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT 58	

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 2 4 7 7 1 2 0 5 7 8 8 0 1 0 4 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, service water pump No. 25, which was one of
03 three pumps supplying the essential header, became inoperable. When an
04 essential header could not be reestablished as per Tech. Spec. 3.3.F.2,
05 a shutdown was begun. Upon restoration of the required essential
06 header, the shutdown was terminated, and the unit was returned to full
07 power.

0 8 7 8 0 8

09		WA		E	B	PUMP	XX	Z	
7	8	9	10	11	12	13	14	15	
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE	
78		—		035		03		L	
21		22		23		24		25	
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD		HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
C	Z	B	Z	0007	N	Y	N	L095	
33	34	35	36	37	40	41	42	43	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A Layne and Bowler, vertiline close coupled pump, Model No. 350SW16F3,
1 1 | became inoperable as a result of a broken shaft, attributable to worn
1 2 | bearings. A pump servicing the non-essential header was installed in
1 3 | its place, thereby reestablishing an essential header. The pump was
1 4 | subsequently overhauled and returned to service.

8 9
FACILITY STATUS
1 5 E 28
7 8 9
% POWER
1 0 0 29
10 12 13
OTHER STATUS 30
44
METHOD OF DISCOVERY
A 31
45 46
DISCOVERY DESCRIPTION 32
Supervisory Panel Instrumentation
80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES	
NUMBER	DESCRIPTION (41)
000	(40) NA

8		9		11		12		
LOSS OF OR DAMAGE TO FACILITY								(43)
TYPE				DESCRIPTION				
1	9	Z	(47)	NA				

7 8 9 10
PUBICITY
ISSUED DESCRIPTION (45) 790112 0128
(2) (0) (N) (44) (NA)
7 8 9 10 68 69 80
NRC USE ONLY

NAME OF PREPARER John M. Makepeace

PHONE: 914-739-8823

NRC USE ONLY