

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

June 8, 1979

Re: Indian Point Unit No. 2  
Docket No. 50-247

Mr. Royce H. Grier, Director  
Office of Inspection and Enforcement  
Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406


Dear Mr. Grier:

This letter supplements our May 1, 1979 letter and completes our response to IE Bulletin No. 79-04.

Since our initial investigation, the Velan Engineering Corporation has conducted a review of their swing check valves provided for Indian Point Unit No. 2. A listing of these valves is presented in Attachment 1. This review involved a comparison of calculated valve weights to the valve weights noted on the engineering drawings for the facility. Velan has advised us that in all cases the weight of Velan check valves furnished for Indian Point Unit No. 2 are within 10% of the weight noted on their drawings and are within normal acceptable tolerances.

Should you or your staff have any questions, please contact us.

Very truly yours,



William J. Cahill, Jr.  
Vice President

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

Mr. T. Rebelowski, Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, N. Y. 10511

WJ  
CCP

7908070043

ATTACHMENT 1

<u>Valve #</u>	<u>Valve Size</u>
210 A&E	3"
374	3"
755 A&B	3"
790	3"
770	6"
849 A&E	4"
852 A&E	4"
838 A-D	6"