

William J. Cahill, Jr.
Vice President

CENTRAL FILES

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

October 25, 1979

Re: Indian Point Unit No. 2
Docket No. 50-247


Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Grier:

Attached is Addendum No. 1 to Appendix B of our September 28, 1979 response to IE Bulletin No. 79-14. This Addendum consists of two "Summary Results" sheets (for lines 356 and 361), both inside containment. These lines were included as part of the text in said response; however, the pertinent "Summary Results" sheets were inadvertently omitted from Appendix B and should be included therein.

Should you or your staff have any questions, please contact us.

Very truly yours,



William J. Cahill, Jr.
Vice President

attach.

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Darrell G. Eisenhut, Acting Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. T. Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, N. Y. 10511

AOI
2
7911270501
CCP

APPENDIX B

ADDENDUM NO. 1

Additional "Summary Results" Sheets For
Statically Analyzed Line Verification
Program

Consolidated Edison Company of New York, Inc.
Indian Point Unit No. 2
Docket No. 50-247
October, 1979

PREPARED BY _____

SUBJECT

SUMMARY RESULTS - IE BULLETIN 79-14
INSIDE CONTAINMENT INSPECTIONS

LINE No. 356

SYSTEM Safety Inj. Syst

INSPECTION ELEMENTS:

<u>DWG. No. (OR CUT No.)</u>	<u>REV. No.</u>	<u>DATE</u>
9321 - F - 2614	19	6/28/79
9321 - F - 2615	17	4/19/79
9321 - F - 2617	22	6/29/79
9321 - F - 2562	23	6/29/79

RESULTS:

DISCREPANCIES

None

RESOLUTION

PREPARED BY _____

SUBJECT

SUMMARY RESULTS - IE BULLETIN 79-14
INSIDE CONTAINMENT INSPECTIONS

LINE No. 361

SYSTEM Residual Ht. Exch.

INSPECTION ELEMENTS:

<u>DWG. No. (OR CUT No.)</u>			<u>REV. No.</u>	<u>DATE</u>
9321	- F -	2561	11	6/29/79
9321	- F -	2562	23	6/29/79
9321	- F -	2617	22	6/29/79

RESULTS:

DISCREPANCIES

SR - 724 - Reinstall Clip
 SR - 728 - " "
 SR - 729 - " "

RESOLUTION

Installed five new snubbers in place.