

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

January 24, 1980

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Grier:

This letter is in response to item 6 of IE Bulletin 79-17 Rev. 1, requiring a report of inspection results within thirty days.

During the period from December 19 to 27, 1979 the normally accessible piping lines 2 1/2 inches or greater in diameter, of the Safety Injection System (SIS), Auxiliary Coolant System (ACS), and the Chemical and Volume Control System (CVCS), were visually inspected for indications of leakage past or present. No indications were identified.

In the future, results of visual inspections performed monthly or during cold shutdowns will be documented and be available at the site for your inspector's review. The results of the visual inspections will be reported in accordance with item 4 of the bulletin only when leak indications are identified. All other inspections will continue to be reported as required in the bulletin.

Very truly yours,



William J. Cahill, Jr.
Vice President

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

Mr. T. Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, N.Y. 10511

8003040307