



ARCTIC PIPE INSPECTION, INC.

Area Code 907 • 283-4471

P. O. Box 1296

KENAI, ALASKA 99611

23 DECEMBER 2009

U.S. NUCLEAR REGULATORY COMMISSION
ATTN: DOCUMENT CONTROL DECK
WASHINGTON, DC 20555

REFERENCE: NRC INSPECTION REPORT 030-12538/09-01 AND
NOTICE OF VIOLATION
DOCKET: 030-12538, LICENSE 50-17314-01

This is our response to the Inspection Report and Notice of Violation as referenced above.

On November 12, 2009, the inspection was performed by Larry Donovan. At this time the API watchman, Seith Ahler, escorted Mr. Donovan at the facility. Mr. Ahler did not have the keys or availability to the radiation records. Mr. George Notter, the shift foreman was at Prudhoe Bay on his 2 week rotation.. We apologize that the records were not available for review during Mr. Donovan's inspection.

The responses will reference the items in the Notice of Violation:

- A. The content of the radiation protection program has been reviewed by the Royce Roberts, President/RSO, in 2009, documented and attached. For the periods from 2004 through 2009, the source, 3M 4F6H, S/N 72482 was in storage, see B. for this documentation of inventory and C. for the leak test record. There were no changes to the radiation protection program. The RSO, Mr Roberts made periodic visits to Kenai and reviewed radiation safety and procedures with his employees. There is no formal documentation of his review prior to 2009. This annual review will be completed in 2010 and until the licensed is in effect.
- B. The physical inventory for 3M 4F6H, S/N 72482 is attached. This shows that the source was inventoried from 1995 to 2009 at six month intervals.
- C. The leak test for source 3M 4F6H, S/N 72482 is attached. This leak test is dated April 12, 2004 by Nuclear Sources and Services, Inc.

If you have any question, please contact me at 281-732-1515.

Royce Roberts
President/RSO

cc: U.S. Nuclear Regulatory Commission
Regional Administrator Region IV
612 East Lamar Blvd, Suite 400
Arlington, TX 76011-4125

Attachments

IE07
R&N IV



ARCTIC PIPE INSPECTION, INC.

Area Code 907 • 283-4471

P. O. Box 1296


KENAI, ALASKA 99611

**ANNUAL REVIEW OF RADIATION SAFETY PROTECTION PROGRAM
ARCTIC PIPE INSPECTION, INC
LICENSE NUMBER 50-17314-01**

Elements of the Radiation Safety Program for Arctic Pipe Inspection, Inc:

- Certificates for the operators
- Log for use, opening and closing of the exposure device
- Inventory records
- Storage requirements
- Leak Test Requirements
- Calibration of Survey Meters

I have reviewed the above elements and the current amendment of the above license.



Royce Roberts
President/RSO

Date: 12-23-09



SEMIANNUAL RADIOACTIVE SOURCE INVENTORY CHECK

Kenai Alaska Plant

Source Serial Number: **72482**

Note: not in use, in storage

Date	Checked by:
1/30/95	George Natter
7/28/95	George Natter
1/3/96	George Natter
7/30/96	George Natter
12-3-96	George Natter
6-27-97	George Natter
1/3/98	George Natter
7/8/98	George Natter
1/16/99	George Natter
7-24-99	George Natter
12/29/99	George Natter
6-1-2000	George Natter
12/28/00	George Natter
5/30/01	George Natter
1/17/02	George Natter
7/18/02	George Natter
1-7-03	George Natter
7-1-03	George Natter
1-10-2004	George Natter
7-12-04	George Natter
1-8-2005	George Natter
7/1/05	George Natter
12-29-05	George Natter
6-19-2006	George Natter
12-6-06	George Natter
6/2/07	George Natter
12/29/07	George Natter
5/30/08	George Natter
12-16-2008	George Natter
6/2/08	George Natter
12/27/08	George Natter
6-15-09	George Natter

[illegible]



NUCLEAR SOURCES & SERVICES, INC.

P. O. BOX 34042

HOUSTON, TEXAS 77034

AREA CODE 713 / 641-0391

SEALED SOURCE LEAK TEST CERTIFICATE

ARCTIC PIPE INSP

BOX 1296

KENAI

, AK

99611

ATTN OF: RADIATION SAFETY

044230

DISC 694 FILE 1944

MO. _____ MO. _____

TEST DUE: 02-02-1964

RADIONUCLIDE CS-137

ACTIVITY 1.5 CI

SERIAL NO. 72482

WIPE DATE 032704

WIPED BY K WALKER

THE ABOVE SOURCE WIPE TEST HAS BEEN ASSAYED IN ACCORDANCE WITH OUR RADIO-ACTIVE MATERIAL LICENSE AND THE APPROPRIATE REGULATORY REQUIREMENTS. THE REGULATIONS DEFINE A LEAKING SOURCE AS ONE FROM WHICH AN APPROPRIATE WIPE TEST HAS REMOVED 0.005 MICROCURIE OR MORE OF ACTIVITY.

THE REMOVABLE ACTIVITY WAS ASSAYED TO BE:

1.43E-05 MICROCURIE

ASSAY NO. 020204 50

DATE 04-02-64

ASSAYED BY RDG

CUSTOMER REPORT