

FEB 5 1968

R. S. Boyd, Assistant Director  
for Reactor Projects, DRL  
THRU: Saul Levine, Assistant Director  
for Reactor Technology, DRL

R. C. DeYoung, Chief  
Containment & Component Technology Branch  
Division of Reactor Licensing  
INDIAN POINT 2 CONTAINMENT LINER BUCKLE

DRL:C&CTB:RCDeY

RT-385

50-247

Dr. Gluckmann has completed his review of the information submitted to us in the January, 1968 report concerning the containment building liner plate buckle. We have concluded that the repair measures taken to correct the buckle were adequate and that an acceptable structural fix has been made.

In the event a formal report is to be submitted, we suggest that the applicant be advised to include more detailed and definitive bases for the conclusions presented in the report.

cc: D. R. Muller, DRL  
K. Kniel, DRL  
J. P. O'Reilly, CO

Distribution:

Suppl. ←  
DRL Reading  
AD/RT Reading  
C&CTB Reading

bcc: S. Levine  
A. Gluckmann  
R. C. DeYoung

8111230101 680205  
ADOCK 05000247

OFFICE ▶	DRL	DRR				
SURNAME ▶	RCDéYoung:rbe	SLevine				
DATE ▶	2/2/68	2/2/68				