

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Heartland Cardiology, LLC 1011 Bowles Avenue, Suite 205 Fenton, MO 63026 REPORT NUMBER(S)		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) 030-36597	4. LICENSEE NUMBER(S) 24-32521-01	5. DATE(S) OF INSPECTION December 14, 2009	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:


- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Robert P. Hays		12/14/09

12/15

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Heartland Cardiology, LLC		2. NRC/REGIONAL OFFICE Region III	
REPORT NUMBER(S) 2009-001		2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 03036597	4. LICENSE NUMBER(S) 24-32521-01	5. DATE(S) OF INSPECTION December 14, 2009	
6. INSPECTION PROCEDURES USED 87130 (10/24/02)		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Janet Myron, NMT	4. TELEPHONE NUMBER 636-680-5151
------------------------------------	-------------------------	--	--

Main Office Inspection Next Inspection Date: **December 2014**

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee was a cardiology clinic located in Fenton, Missouri, with authorization to use any byproduct material as needed permitted by 10 CFR 35.200. Licensed activities were conducted only at the location indicated on the license. The nuclear medicine department was staffed with one nuclear medicine technologist (NMTs). The NMT conducted 1-6 diagnostic cardiac patient studies, rest and stress, only on Mondays and Fridays each week. Licensed material is received as unit doses from a local nuclear pharmacy. All waste was either held for decay-in-storage (DIS) or returned to the nuclear pharmacy. No change in NMT since the previous inspection. The inspector performed independent and confirmatory radiation measurements which indicated results consistent with licensee survey records and postings.

Performance Observations

Interviews with licensee personnel indicated adequate knowledge of radiation safety concepts and procedures. The licensee's NMT demonstrated/discussed: (1) unit dose prep and safe use; (2) package check-in and return procedures; (3) wipe test counting; (4) dose calibrator tests; (5) security of license materials; (6) quarterly radiation safety program reviews; (7) surveys; (8) sealed source inventory; (9) dosimetry; and (10) any minor contamination events (none).