

William J. Cahill, Jr.
Vice President


Regulatory Docket File

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

September 15, 1975

RE: Indian Point Unit No. 2
Docket No. 50-247

Mr. Robert W. Reid, Chief
Operating Reactors Branch #4
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555



Dear Mr. Reid:

In response to Mr. George Lear's letter of June 18, 1975, Con Edison has been discussing with the Staff the concern of potentially submerged valves within the vapor containment building and the analysis that was submitted on July 9, 1975 evaluating the emergency core cooling system performance at Indian Point Unit No. 2. Con Edison has recently received information from the various vendors which are involved in the postulated flooding of valve motors following a LOCA and is presently reviewing this information.

Final resolution of these items will require further discussions with the Staff and as the information becomes available to respond, Con Edison will submit the required analyses to the Commission. In any case, it is anticipated that these analyses will be submitted such that the Staff will have at least ninety (90) days for review prior to commencement of operation with the first reload region at Indian Point Unit No. 2. The first refueling outage is currently scheduled to commence April 1, 1976.

Very truly yours,

William J. Cahill, Jr.
Vice President

mp

8111100123 750915
PDR ADOCK 05000247
PDR

9865