

Regulatory

File Cy

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N. Y. 10003 Telephone (212) 460-5133

May 21, 1975

Re Indian Point Unit No. 2 Docket No. 50-247

Mr. George Lear, Chief Operating Reactors Branch #3 Division of Reactor Licensing Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Lear

In response to your letter of March 14, 1975 concerning long-term chemical concentration changes in the core following a postulated loss-of-coolant accident (LOCA), we provided a copy of our procedure E-2 with our letter of April 29, 1975 from William J. Cahill, Jr. As this procedure indicates, the Indian Point Unit No. 2 facility does have (the capability to inject the safety injection flow into a hot leg during the recirculation phase of a postulated LOCA.

We are unable at this time, however, to complete our review to determine if additional procedures or procedural changes are required until the Westinghouse Electric Corporation resolves this issue on a generic basis with the Commission. This resolution is expected by July 21, 1975, at which time we will be able to complete our response to your inquiry.

Very truly yours

bail L. Neuman

Carl L. Newman Vice President

mk

8111100131 750521 PDR ADUCK 05000247 P PDR

5674