

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

February 15, 1979

Re: Indian Point Station
Unit No. 2
Docket No. 50-247


Mr. William G. McDonald, Director
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. McDonald:

Enclosed you will find two (2) copies of the monthly operating report relating to Indian Point Unit No. 2 for the month of January, 1979.

Unit No. 2 Technical Specification 3.5.5 requires reporting of the removal of the cover plate on the rear of the control room safeguards panel. During the year 1978, this cover was removed once with the approval of the Operations Staff. The cover was removed on April 12, 1978, in order to install connections for the performance of Surveillance Test PT-R-13 and was replaced on May 23, 1978.

Very truly yours,



enc.

cc/ Mr. John G. Davis, Acting Director (40 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Mr. Ted C. Cintula
Office of Management & Program Analysis
Mail Stop 12105
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Handwritten: A008
15/11

7902210 239