August 23, 1974

Action Pla.

Mr. Harold D. Thornburg, Chief Field Support & Enforcement Branch Directorate of Regulatory Operations U.S. Atomic Energy Commission Washington, D.C. 20545

Dear Mr. Thornburg:

Last February you sent me a copy of the documents mentioned in your attached letter. Do you have a copy of the final report mentioned in your letter that you can send me. Also, the November 30 letter on the sequence leading to the pipe rupture is a only a supplement to a November 14th letter from ConEd. I would appreciate it very much if you would send me the final report, which presumably analyzes the **XEM** cause of the pipe failure, and the Nov. 14th letter? I am trying to **fi** learn from the reports and letters information relating to the likely modes or mode by which a heavy pipe like that would **fi** fail.

Sincerely yours whad Ellebli

Richard E. Webb 2613-102 St. Toledo, Ohio 43611

Consolidated Edison Indian Painto 2

