


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

April 27, 1976
Re Indian Point Unit No. 3
Docket No. 50-286
R.O. -76-3-4(B)




Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406

Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64 the attached report of Reportable Occurrence R.O.-76-3-4(B) is submitted. This report fulfills the requirement for a written report within 30 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.



Very truly yours,

William J. Cahill, Jr.
Vice President

Enc:
WJC:nvg

Copy to Director of Nuclear Reactor Regulation
ATTN: Mr. Donald F. Knuth, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William F. McDonald, Director (3 copies)
Office of Management Information and Program
Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

4281