

Comanche Peak Nuclear Power Plant, Units 3 & 4
 COL Application
 Part 2, FSAR




Figure 2.5.2-223 Deaggregation of 10^{-4} Rock Hazard for 5 and 10 Hz