

Vice President

REC. NUMBER
PROD. & UTIL. EAG. 50-247

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 469-3010

December 28, 1972

Re Indian Point Unit No. 2
AEC Docket No. 50-247


Mr. Angelo Giambusso, Deputy Director
for Reactor Projects
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20045

Dear Mr. Giambusso

The Directorate of Licensing letter, dated December 19, 1972, requested a review of Indian Point Unit No. 2 to determine whether a postulated pipe failure in the main steam or feedwater lines outside of containment would result in damage to the auxiliary feedwater system.


We plan to submit the analysis of this postulated accident situation for Indian Point Unit No. 2 by March 30, 1973. If the results of the analysis indicate that modifications to the facility are necessary, we will also provide a description and estimates of the schedule for design, fabrication and installation of the modifications.

Very truly yours



William J. Cahill, Jr.
Vice President

md



8110310744 730123
PDR ADOCK 05000247
G PDR