



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-

OCT 24 1969

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch,
Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2 (IP-2)
DOCKET NO. 50-247

The attached report of visits to the subject facility on August 26, 27
and 29, 1969 and September 10, 1969, is forwarded for information.

Con Ed's investigation into the previously reported pipe deficiency allega-
tions appears to be proceeding in a satisfactory manner.

The effectiveness of the Westinghouse reorganization (Wedco) will be watched
closely during future visits including specifically a special QC inspection
at IP-2 and the initial QA inspection at IP-3, both scheduled for the near
future. It is our understanding that Con Ed plans to amend the application
in this regard, however, we have no firm commitment as to the timing.

Regarding the areas in question pertaining to required separation of redundant
cables, this and other selected electrical areas are tentatively scheduled to
be reviewed in general detail during the aforementioned QC inspection and
pending the applicant's response to outstanding DRL questions on related
electrical criteria*.

*Letter, Morris to Anderson, dated August 4, 1969.

R. T. Carlson
R. T. Carlson
Senior Reactor Inspector

Enclosure:
CO Report No. 247/69-9
by G. L. Madsen
dated 10/17/69

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
Regional Directors, CO
REG files

8111030016 691024
PDR ADOCK 05000247
Q PDR