

UNITED STATES ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE REGION I

970 BROAD STREET NEWARK, NEW JERSEY 07102 201 645-3944

October 31, 1969

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Br., Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2 (IP-2) DOCKET NO. 50-247

The attached report of inspection visits to the subject facility on September 30 and October 1-2, 1969, is forwarded for information.

We have expressed our concerns to Con Ed management regarding the potential for the Westinghouse reorganization (Wedco) developing into an unacceptable situation. They have assured us that this matter is receiving their careful attention. Subsequent to these visits we learned that Con Ed plans to amend their application in this regard, possibly within the next month. We will continue to monitor this area closely.

Additional observations of questionable acceptability were noted in the electrical cable separations area. Con Ed is directing attention to this matter.

Deviations from applicable material specifications and questionable conformance with applicable code requirements have been identified with regard to eight check valves in the safety injection system. The results of a review initiated by Con Ed to determine the applicability aspects of this subject will be reviewed by our inspector during the next visit.

Weld overlay is scheduled to be applied to both the ID and the OD of the eight reactor vessel nozzles.

Two and possibly a third area of discrepancy between the asbuilt and present FSAR requirements for the fuel storage building will be resolved by amending the application. Fuel for the first core is now being received at the site.

M.E. Moule 6 R. T. Carlson

Senior Reactor Inspector

Attachment:

CO Report No. 247/69-10 by G. L. Madsen, Dtd 10/28/69

cc: E. G. Case, DRS

R. S. Boyd, DRL (2)

S. Levine, DRL (6)

D. J. Skovholt, DRL (3)

L. Kornblith, Jr., CO

Regional Directors, CO

√ REG File