

UNITED STATES GOVERNMENT

Memorandum

TO : J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Branch, Division of Compliance, HQ DATE: April 4, 1968

FROM : *N. C. Moseley*
N. C. Moseley, Senior Reactor Inspector
Region I, Division of Compliance

SUBJECT: CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2
DOCKET NO. 50-247

The attached report of a visit by our field inspector to the subject facility on February 27 and 28, 1968, is forwarded for information. No safety problems were noted.

The previously identified containment liner bulge has been satisfactorily resolved. Two additional bulge areas have been detected and the licensee is actively pursuing corrective action.

Consolidated Edison has enlarged the excavation blasting monitoring program since our previous visit. The program now appears to be adequate.

The concrete batch plant for Indian Point No. 2 has been in use for many years and lacks the sophistication of more modern plants. As a result, Con Ed, and its contractors, are providing close follow up of the quality of the concrete from the plant. Our review indicates that satisfactory quality has been maintained. We will continue to review this area closely in future visits.

Attachment:

CO Rpt. No. 247/68-1
by G. L. Madsen
dtd 4/1/68

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
Regional Directors, CO
REG files ✓

8111030282 680404
PDR ADOCK 05000247
G PDR

