



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

REG files

201 645. 3942

Docket #
50-247

May 26, 1970

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch,
Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY - INDIAN POINT NO. 2
DOCKET NO. 50-247

The attached report of a visit to the subject facility on April 10,
21 and 22, 1970 is forwarded for information.

We expressed concern in the forwarding letter accompanying the last
inspection report about the lack of progress in preparing preopera-
tional testing procedures. During this inspection schedules and dead-
lines for preparation of individual procedures were shown to the in-
spector. Wedco representatives stated that schedules had been prepared
earlier, but were not finalized because of uncertainties in the construc-
tion schedule. We will continue to follow developments in this area
closely.

When the acceptability of the 8 safety injection accumulator check
valves was first questioned, it appeared that the discrepancy was
minor and that resolution would be no problem. At this time, however,
it appears that replacement may be the only resolution. We know that
these valves were part of a group order, but we do not know which
specific plants received the other valves. We will follow this prob-
lem closely in the future.

Auditing of the separation of redundant instrument and electrical cables
is being done by Con Ed. We expect to get more action in this area by
Wedco in the future.

No concrete was pumped through aluminum pipe during the construction of
this facility.

N. C. Moseley
N. C. Moseley
Senior Reactor Inspector

Enclosure:
CO Report No. 247/70-4
by G. L. Madsen
dated 5/15/70

8111120618 700526
PDR ADDCK 05000 247
Q PDR

cc: E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
T. R. Wilson, DRL
P. W. Howe, DRL (2)
L. Kornblith, CO
Regional Directors, CO
REG files