

UNITED STATES ATOMIC ENERGY COMMISSION DIVISION OF COMPLIANCE REGION I

970 BROAD STREET NEWARK. NEW JERSEY 07102 MAR 6 1970

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Br. Division of Compliance, Heasquarters

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2 (IP-2) DOCKET NO. 50-247

The attached report of a management meeting held at the corporate offices of Consolidated Edison Company on February 10, 1970, is forwarded for information.

The findings of the in-depth quality control audit, which was performed during December, 1969, were discussed with Con Ed and their principal contractors. The licensee was responsive to the comments and indicated that the items discussed will be acted upon.

Items of major concern are associated with the control of installation and adequacy of design of the electrical systems, mostly in the area of separation of redundant channels. Westinghouse and Con Ed have indicated actions to be taken relative to these concerns; however, some of the resolution cannot be reached until DRL takes a position relative to design adequacy.


An item of secondary interest is associated with the surface conditions identified on the safety injection system. If Con Ed and Westinghouse perform a final surface and cleanup as promised, this should not be a difficult item to resolve.

Con Ed informed us that core loading is now scheduled for August 10, 1970.

R. T. Carlson Senior Reactor Inspec

PDR

Attachment: CO Report No. 247/70-1, by G. L. Madsen, dated 2/27/70







201 645-