



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645.

JUN 14 1972

J. B. Henderson, Chief, Reactor Construction  
Branch, Regulatory Operations, HQ

CONSOLIDATED EDISON COMPANY  
INDIAN POINT UNIT 2  
RO REPORT NO. 50-247/72-07

The subject inspection report is forwarded for information.

This inspection was directed toward those construction and/or repair items including the condensate storage tank failure, accumulator check valves, main steam safety and relief valves, and fire damage to the primary auxiliary building.

Work is not yet completed on the accumulator check valves and main steam safety and relief valves; however, procedural control appears to be satisfactory for completion of the required work.

*E. M. Howard*  
E. M. Howard, Chief

Reactor Construction Branch, RO:I

Enclosure:  
Subject Inspection Report

cc: R. Minogue, RS (3)  
R. S. Boyd, L (2)  
R. C. DeYoung, L (2)  
D. J. Skovholt, L (3)  
H. R. Denton, (2)  
P. A. Morris, RO  
R. H. Engelken, RO  
AD for Procedures, RO  
J. G. Keppler, RO  
RO Files  
DR Central Files ✓

8111110619 720614  
PDR ADDCK 05000247  
Q PDR