



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3942

April 5, 1972

J. B. Henderson, Chief, Reactor Construction
Branch, Division of Compliance, HQ.

CONSOLIDATED EDISON COMPANY
INDIAN POINT 2
CO REPORT NO. 50-247/72-04

The subject inspection report is forwarded for information.

The licensee had not completed a report of the cause of the condensate storage tank failure at the time of the inspection. This report will be reviewed during subsequent inspections. Additional information required by Con Ed letter of December 6, 1971, relative to the fire damage, will be reviewed upon completion of the report by the Con Ed Engineering Division.

E. M. Howard
for E. M. Howard
Senior Reactor Inspector

Enclosure:
Subject Inspection Report

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
J. G. Keppler, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
CO Files
DR Central Files ✓

811110935 720405
PDR ADDCK 05000247
PDR
Q