

UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645-3942

FEB 25 1972

J. G. Keppler, Chief, Reactor Testing & Operations Br.  
Division of Compliance, HQ

CO INQUIRY REPORT NO. 50-247/72-06  
CONSOLIDATED EDISON COMPANY  
IP- 2  
RESIDUAL HEAT REMOVAL SYSTEM - HEAT EXCHANGER FAILURE

The subject inquiry report is forwarded for your information.


The licensee actions on this matter are considered appropriate.  
Determination of the failure mechanism may indicate an applicability  
to other similar plants.

The licensee does not consider this matter reportable to the  
Division of Reactor Licensing. Our inspector will follow up on  
this item during future inspections.

Eldon J. Brunner  
Senior Reactor Inspector

Enclosure:  
Subject Inquiry Report

cc: E. G. Case, DRS (3)  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
H. R. Denton, DRL (2)  
L. Kornblith, CO  
R. H. Engelken, CO  
Regional Directors, CO  
CO Files  
DR Central Files ✓



811111014 720225  
PDR ADOCK 05000247  
Q PDR