

CO Inquiry Report No.: 50-247/71-05

Subject: Consolidated Edison Company

Indian Point 2

Docket No.: 50-247

License No.: CPPR-21

Descriptive Title: Primary System Cleaning

Prepared by: *Eldon J. Brunner*
Eldon J. Brunner, Sr. Reactor Inspector

10/14/71
Date

A. Date and Manner AEC was Informed:

During a site inspection on October 5, 1971, Mr. Dadson informed G. L. Madsen of the finding of debris behind the temporary primary system "blocks" installed during the steam generator repair.

B. Description of Particular Events or Circumstances:

Temporary "blocks" were installed in primary coolant pipes to maintain cleanliness of the primary system during the repair of the steam generators. Upon removal of these "blocks", dirt, slag, dye penetrant developer and water were found in the pipes behind the blocks.

C. Actions by the Licensee:

The reactor vessel internals will be removed and a visual inspection will be performed. The primary system will be cleaned using the same procedure used for the initial cleanup. Cleanup, inspection and reinstallation of internals is expected to be completed by October 10, 1971.

811120441 711014
PDR ADCK 05000247
PDR
Q