



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION 4  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645.3942

JUL 1 1971



J. P. O'Reilly, Chief, Reactor Testing and  
Operations Branch, Division of Compliance, HQ

CO INQUIRY REPORT NO. 71-2  
CONSOLIDATED EDISON COMPANY (INDIAN POINT NO. 2)  
STEAM GENERATOR CLADDING SEPARATION

The attached Inquiry Report is forwarded for information. The steam generator cladding separation appears similar to the condition encountered at the Carolina Power and Light (H. B. Robinson No. 2) plant. We will continue to review this item during future inspections at the site.

*G. S. Moseley/for.*  
N. C. Moseley  
Sr. Reactor Inspector

Enclosure:  
CO Inquiry Report No. 71-2

cc: E. G. Case, DRS (3)  
P. A. Morris, DRL  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
H. R. Denton, DRL (2)  
A. Giambusso, CO  
L. Kornblith, CO  
R. H. Engelken, CO  
Regional Directors, CO  
✓ REG Files

8111120650 710701  
PDR ADDCK 05000247  
Q PDR