



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION 4
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645.3942

30-247

JUL 1 1971



J. P. O'Reilly, Chief, Reactor Testing and
Operations Branch, Division of Compliance, HQ

CO INQUIRY REPORT NO. 71-2
CONSOLIDATED EDISON COMPANY (INDIAN POINT NO. 2)
STEAM GENERATOR CLADDING SEPARATION

The attached Inquiry Report is forwarded for information. The steam generator cladding separation appears similar to the condition encountered at the Carolina Power and Light (H. B. Robinson No. 2) plant. We will continue to review this item during future inspections at the site.

G. S. Maden/for.
N. C. Moseley
Sr. Reactor Inspector

Enclosure:
CO Inquiry Report No. 71-2

- cc: E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
A. Giambusso, CO
L. Kornblith, CO
R. H. Engelken, CO
Regional Directors, CO
✓ REG Files

8111120650 710701
PDR ADDCK 05000247
Q PDR