

*Reactor Facilities
Branch*

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

MAR - 5 1976

Consolidated Edison Company of
New York, Inc.
Attention: Mr. W. J. Cahill, Jr.
Vice President
4 Irving Place
New York, New York 10003

License No. DPR-5
DPR-26
Insp. Nos. 75-11
75-20
Docket Nos. 50-003
50-247

Reference: Your letter dated February 17, 1976
In response to our letter dated January 23, 1976

Gentlemen:

Thank you for informing us of the corrective and preventive actions you documented in response to our correspondence. These actions and the information in your response to Deficiency C, will be evaluated further during a subsequent inspection of your licensed program.

Based on telephone call on February 23, 1976 between Mr. Van Wyck of your staff and Mr. Reynolds of this office, it is our understanding that you are aware that the self reading dosimeter referred to on page 8 of your response does not meet the requirements of Technical Specification 6.13.1a. The device required by the technical specification is a continuously indicating, dose-rate instrument.

Sincerely,

James P. O'Reilly
James P. O'Reilly
Director

cc: A. E. Upton, Esquire
W. Stein, Manager, Nuclear Power Generation Department
S. Salay, Plant Manager
J. M. Makepeace, Director, Technical Engineering
A. Z. Roisman, Counsel for Citizens Committee for
Protection of the Environment

bcc:
IE Mail & Files (For Appropriate Distribution)
PDR
Local PDR
NSIC
TIC

REG:I Reading Room
State of New York

8111190990 760305
PDR ADOCK 05000003
Q PDR