

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 469-3819

June 30, 1975

Re: Indian Point Station
Unit No. 2
Docket No. 50-247


Mr. Eldon J. Brunner, Chief
Reactor Operations Branch
U.S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Brunner,

This refers to your letter of June 6, 1975 concerning an inspection of our Unit No. 2 facility by Mr. Fasano of your office. Based on the results of this inspection, you stated it appeared that one of our activities was not conducted in full compliance with NRC requirements. Specifics relating to this item were set forth in the Notice of Violation enclosed as Appendix A to your letter.

With regard to this item of noncompliance, installation of both jumpers was authorized over the phone by the Operations Engineer. The Watch Foreman, however, did fail to note on the jumper log that proper authorization had been given for installation of the jumper. The Watch Foreman involved in this matter was spoken to by the Operations Engineer and reminded of the importance of filling out forms properly and in accordance with established administrative policies. In addition, this matter has been discussed with the other Unit No. 2 Watch Foremen and the importance of properly filling out forms re-emphasized.

Very truly yours,



William J. Cahill, Jr.
Vice President

811240282 750716
PDR ADDCK 05000247
Q PDR