

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

October 26, 1976

Indian Point Station
Docket Nos. 50-247
50-286

Mr. Eldon J. Brunner, Chief
Reactor Operations and Nuclear Support Branch
U.S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Brunner

This refers to an inspection conducted by your Mr. J. Streeter and other members of your office on August 30 - September 4 and 10, 1976 of activities authorized by NRC License Nos. DPR-26 and DPR-64 at our Indian Point Station. Your October 1, 1976 letter stated that it appeared that certain of our activities were not conducted in full compliance with NRC requirements. These items of apparent non-compliance were set forth in the Notice of Violation which was enclosed as Appendix A to your October 1, 1976 letter. Our response to these items is as follows:

Item A (Infraction)

The diagram error in the control circuitry for the safety injection pumps for Indian Point Unit No. 2 was investigated and found to be the result of a human error, and not a deviation from procedures. Individuals directly involved were cautioned to exert greater diligence and awareness in their performance of work

8111240401 761202
PDR ADOCK 05000247
G PDR

William J. Cahill, Jr.
Vice President


-2-

October 26, 1976

Item B (Deficiency)

CI-240-1 (Quality Assurance Program For Operating Nuclear Plant) is being revised so that the description of an individual's duties and responsibilities will not be required to be in Position Descriptions. Detailed duties and responsibilities of individuals are defined in procedures and manuals. These details are more relevant to an individual's QA program efforts and are kept up-to-date. Position Descriptions tend to be more general and are updated less frequently.

Very truly yours



William J. Cahill, Jr.
Vice President