

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

November 27, 1979

Indian Point Station
Docket No. 50-247

Mr. Eldon J. Brunner, Chief
Reactor Operations and Nuclear Support Branch
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission, Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406


Dear Mr. Brunner

This refers to Inspection 50-247/79-20 conducted by Mr. R. Zimmerman, Reactor Inspector, on October 2-5, 1979, of activities authorized by NRC License No. DPR-26 at Indian Point Station. Your October 31, 1979 letter stated that it appeared that one of our activities was not conducted in full compliance with NRC requirements; as set forth in the Notice of Violation enclosed therewith as Appendix A. Our response to this item of noncompliance is as follows:

The temporary procedure change discrepancies identified by your inspector have been corrected. In addition, the Operations Subsection Temporary Procedure Change and Procedure books have been reviewed to insure no similar discrepancies exist.

In order to prevent recurrence, the Operations Subsection Administrative Directive for procedure has been revised to require identification of the date or conditions for expiration on the temporary procedure change form itself. This will insure the proper identification of closed out temporary procedure changes. In addition this Administrative Directive now requires the periodic review of appropriate procedure books to insure inclusion of active temporary procedure change forms.

Very truly yours



8001240379