

John D. O'Toole
Assistant Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-2533

January 6, 1981

Indian Point Station
Docket No. 50-247


Mr. Walter G. Martin, Chief
Safeguards Branch
U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Martin

This refers to Inspection No. 50-247/80-18 conducted by Mr. R.J. Bailey, Physical Security Inspector on October 6-10, 1980 of activities authorized by NRC License No. DPR-26 at Indian Point Station. Your November 25, 1980 letter stated it appeared that certain of our activities were not conducted in full compliance with NRC requirements as reported in Appendix A of your letter. Our response to these items of non-compliance is presented in the attached Appendix A.

In accordance with Section 2.790 (d) of the NRC's Rules of Practice, Part 2, Title 10, Code of Federal Regulations, Correspondence and Reports to or from the NRC which identify a licensee's control and accounting procedures for safeguarding licensed nuclear materials or detailed security measures for the physical protection of a licensed facility are exempt from disclosure. We understand, therefore, that this response will not be placed in the Public Document Room and will receive limited distribution.

Very truly yours



CC: Mr. T. Rebelowski, Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, New York 10511

8103050456