

Murray Selman
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

July 17, 1987

Re: Indian Point Station Unit No. 2
Docket No. 50-247


Mr. Thomas T. Martin, Director
Division of Radiation Safety and Safeguards
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUBJECT: Supplemental Response to Inspection Report 87-14

Dear Mr. Martin:

By letter dated July 10, 1987, we responded to your request, in Inspection Report No. 50-247/87-14, to provide details of our proposed actions to improve our ability to promptly and accurately classify accident conditions. In the fifth paragraph of that letter, we noted that "we have retained independent consultants who possess human factors engineering expertise to provide an objective, third-party analysis of our EAL's." For clarification, while we have met with several consultants on this issue, we anticipate finalizing contractual arrangements in the near future.

Very truly yours,



8707250184 870717
PDR ADOCK 05000247
Q PDR

IEo1
11

cc: U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Mr. William T. Russell
Regional Administrator - Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, NY 10511

Ms. Marylee Slosson, Project Manager
PWR Project Directorate I-1
Division of Reactor Projects - I/II
U.S. Nuclear Regulatory Commission
Washington, DC 20555