

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



May 16, 1978  
IP-JWK-1803

Mr. Boyce H. Grier, Director  
Office of Inspection and Enforcement  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406


Subject: Indian Point 3 Nuclear Power Plant  
Docket No. 50-286

Dear Mr. Grier:

In response to I.E. Bulletin No. 78-05, a survey was conducted in an effort to locate General Electric auxiliary contact mechanisms of the model in question.

As it was determined that none of the GE Model CR105X auxiliary contact mechanisms have been utilized at Indian Point 3, it is our conclusion that the events ascribed in I.E. Bulletin No. 78-05 have no applicability at our facility and no further action is required.

Very truly yours,

  
J. P. Bayne  
Resident Manager

JWK/rbb

cc: Office of Inspection and Enforcement  
Division of Reactor Inspection Programs  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555  
cc: Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

8111050270 780516  
PDR ADOCK 05000286  
G PDR

AO/2